

e-office No → 460568
Receipt No → 5/6/2018

ALL INDIA INSTITUTE OF MEDICAL SCIENCES
ENGINEERING SERVICES DEPARTMENT
Eastern & Western Campus

05/06/2018

Sub: Checking of Ceiling Plaster/Sun Shade

It has been observed that areas susceptible to seepage/dampness there are chances of ceiling chunks/plaster falling in long run. As the toilet/ kitchen area of individual units are not always available for inspection by Engineering Services Department. Therefore It is requested that in case the allottee/ occupant finds any noticeable crack/clipping/withering in the ceiling plaster, it should be immediately brought in notice of JE/AE for urgent & immediate remedial measures. This would help in avoiding any mishap on account of falling plaster/ chunk.

Active co-operation is solicited.


(ER.SANJAY JAIN)
ASSISTANT ENGINEER-II

1. Er. Dinesh J.E.(E.Campus)
Ext.4337, Mob. 9868397872

1. Er. N.Karmakar, J.E.(W.Campus)
Ext.3372, Mob. 9868397859

2. ER.SANJAY JAIN, A.E.(E.Campus)
Ext.4973, Mob. 9868397875

2.ER. SUNIL KUMAR, A.E.(W.Campus)
Ext.4771, Mob. 9868397878

Distribution:

1. CI,CII,DII,E,F,I & G type qtrs.of E.Campus & W.Campus at AIIMS.

Copy to: 1. Superintending Engineer } For Information please.
2. Executive Engineer-II(Civil) } For Information please.

Prof. A. Shariff

Facility Incharge, Computer facility - Please upload on website.

Sh. Sanjeev Kumar for N/A please


06/06/18